

Mövenpick Restaurant

Germany

Mövenpick Restaurant
Potsdam



Christiani Wassertechnik GmbH
Charlottenstraße 18

10117 Berlin

Reference Letter

Dear Sir,

our Mövenpick Restaurant opened in January 2000. After a short period of time we noticed a high level of limescale developing on the ice-cream makers. These calcification's could only be cleared bit by bit which is a time consuming process. To avoid potential losses, a short-term limescale filter was installed. The operating time of this filter is limited however and thus resulted in high costs.

At a trade fair visit we consulted the company Christiani Wassertechnik GmbH about other possibilities. We installed the limescale converter Vulcan 5000 and the ice-cream makers have been functioning smoothly for 10 months now.

The limescale, which accumulates especially in the crushed ice makers, can now be easily removed as it is converted into fine-grained structures.

We wish the company Christiani further success with their excellent products.

Yours Sincerely,

Marcel Charrier
Director

Mövenpick Zur Historischen Mühle Sanssouci
Zur Historischen Mühle
14469 Potsdam
Tel.: 0331 / 78 12 93
Fax 0331 / 281 49 50



Vulcan 5000



Vulcan protecting the ice machine



Vulcan protecting the ice-cream makers



Soft limescale is now easily removed

Mövenpick Restaurant, Potsdam

www.moevenpick.com | Mövenpick Restaurants Deutschland GmbH



Eismaschine



Vulcan 5000



Feine Kornstruktur



Weiche Kalkablagerungen